


**SKODA Octavia: 1HLF959**

Vinnnumber:	<b>TMBJF7NE6F0056596</b>	Versionname:	<b>OCTAVIA COMBI Active</b>
First Registrationdate:	<b>19/08/2014</b>	Fiscalpower:	<b>90PK</b>
Expertise Mileage:	<b>93360</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4507</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>No GPS</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1030,26</b>
Bumper R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Boot carpet, Stain, Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>290,08</b>





Door F L, Scratch(es), Acceptable 0,00

No pictures to display


Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door R R, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20

No pictures to display