


OPEL Insignia: 1FLT715

Vinnumber:	WOLGT8EL5D1122908	Versionname:	INSIGNIA BRE ecofl.Cosmo S/S DPF 130PK
First Registrationdate:	9/08/2013	Fiscalpower:	
Expertise Mileage:	191473	Power Kw:	96
Bodytype:	Break	Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2222
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 0 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1932,86
-------------------	---------

Floor covering F L, Hole, E - Replace	252,00
---------------------------------------	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display