



**RENAULT GRAND SCENIC: 1PDE286**

Vinnnumber:	<b>VF1JZ89AH55589666</b>	Versionname:	<b>1.5 ENERGY DCI 110 LIFE 5P</b>
First Registrationdate:	<b>8/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>98313</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2724</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Luggage cover	
Windows electric F	Front parking sensors	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/96 H Steel</b>			
Summer tyres:	Fr.L.	<b>Fulda: 4 mm</b>	Fr.R.	<b>Fulda: 4 mm</b>
	Re.L.	<b>Fulda: 4 mm</b>	Re.R.	<b>Fulda: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1076,36
-------------------	---------

Outer door handle F L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Door R L, Dent(s), PDR - Knock out without painting	63,00
---	-------



Wing R R, Dent(s), PDR - Knock out without painting 82,80



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

GPS, Missing, E - Replace 50,00



Wheel cover F R, Broken, E - Replace 30,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Deformed / Strained, Le - Replace and paint 651,00



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace 84,00

