



**MERCEDES A: 1HNU902**

Vinnumber:	<b>WDD1760121V028668</b>	Versionname:	<b>A 180CDI BE Edition 109PK</b>
First Registrationdate:	<b>1/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>123130</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>SERVICE A OVERSCHREDEN MET 3200 KM</b>	Parking lot:	<b>3427</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**


	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1034,16</b>
-------------------	----------------

Wheel cover R R, Scratch(es), E - Replace	<b>30,00</b>
---	--------------



Bonnet, Stone chip(s), Acceptable	<b>0,00</b>
-----------------------------------	-------------



Steel rim F L, Deformed / Strained, E - Replace 88,80



Door R R, Dent(s), Acceptable 0,00



Wheel cover F L, Deformed / Strained, E - Replace 30,00



Ignition key, Missing, E - Replace 150,00



SD card, Broken, E - Replace 275,00



Bumper F R, Scratch(es), It - Spot repair 115,56



Wheel cover F R, Scratch(es), E - Replace 30,00



Interior, Dirty, Cleaning 25,00



Wheel arch cover F L, Deformed / Strained, Forfeit 48,00



Maintenance, Maintenance, Execute 0,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Repaired, Acceptable 0,00

