


**OPEL Vivaro 2900: 1DDI380**

|                                    |                                 |              |   |
|------------------------------------|---------------------------------|--------------|---|
| Vinnnumber:                        | <b>W0LJ7B7BACV622611</b>        | Versionname: | <b>VIVARO 2900 COMBI L2H1 Ecof.DPF(E5)115PK</b> |
| First Registrationdate:            | <b>16/04/2012</b>               | Fiscalpower: |   |
| Expertise Mileage:                 | <b>141588</b>                   | Power Kw:    | <b>84</b>                                       |
| Bodytype:                          | <b>Transporter</b>              | Body color:  | <b>Grey</b>                                     |
| Gearbox:                           | <b>MAN 6 VIT</b>                | Paint type:  | <b>Metalic</b>                                  |
| Transmission:                      |                                 | Rims summer: | <b>Steel</b>                                    |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                       |
| Battery functioning:               | <b>Yes</b>                      | Parking lot: | <b>3302</b>                                     |
| Number of doors:                   | <b>5</b>                        |              |   |
| Number of seats:                   | <b>9</b>                        |              |   |
| Number head rests:                 | <b>9</b>                        |              |   |
| Rims summer:                       | <b>Steel</b>                    |              |   |
| Category:                          | <b>Light Commercial Vehicle</b> |              |   |
| Oil level:                         | <b>OK</b>                       |              |   |
| Registration Certificate Car (BE): | <b>No</b>                       |              |   |

**Options**

|                                |                               |                      |                   |
|--------------------------------|-------------------------------|----------------------|-------------------|
| Radio CD                       |                               | Central consol F     |                   |
| Windows electric F             |                               | Rear parking sensors |                   |
| Cruise Control                 |                               | Type of Tow bar      | <b>No Tow bar</b> |
| Steering wheel multifunctional |                               |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |                   |
| Type of GPS                    | <b>No GPS</b>                 |                      |                   |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |                   |
| Type of climate control        | <b>Manual climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

| 205/65/16/107 T Steel |       |                       |       |                       |
|-----------------------|-------|-----------------------|-------|-----------------------|
| Summer tyres:         | Fr.L. | <b>Michelin: 7 mm</b> | Fr.R. | <b>Michelin: 7 mm</b> |
|                       | Re.L. | <b>Michelin: 8 mm</b> | Re.R. | <b>Michelin: 8 mm</b> |

**Assistance equipment**

|             |            |
|-------------|------------|
| Spare wheel | <b>Yes</b> |
|-------------|------------|

|                                       |         |
|---------------------------------------|---------|
| Total cost ex VAT                     | 1439,58 |
| Ignition key, Missing, E - Replace    | 150,00  |
| <i>No pictures to display</i>         |         |
| Wheel cover R L, Missing, E - Replace | 22,50   |



|   |        |
|---|--------|
| Certificate Of Conformity, Missing, E - Replace                     | 150,00 |
| <i>No pictures to display</i>                                       |        |
| Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 165,13 |




Bumper R, Scratch(es), Smart repair 110,64



Door moulding Lower R R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00



Bumper F, Scratch(es), Smart repair 110,64



Registration Document, Missing, E - Replace 150,00

No pictures to display

Wheel cover R R, Missing, E - Replace 22,50



Wheel cover F R, Missing, E - Replace 22,50



Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Bumper F, Deformed / Strained, LI - Repair and paint (complete) 158,85



Wheel cover F L, Missing, E - Replace 22,50



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



|                                   |      |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Windscreen, Repaired, Acceptable  | 0,00 |
| <i>No pictures to display</i>     |      |