



VOLKSWAGEN Sharan: TQ6547			
Vinnnumber:	WVWZZZ7NZEV012804	Versionname:	SHARAN Highline BMT St/St DSG 177PK Aut.
First Registrationdate:	11/11/2013	Fiscalpower:	
Expertise Mileage:	120803	Power Kw:	130
Bodytype:	MPV	Body color	Dark Blue
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3121
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	No Tow bar
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/98 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment	
Total cost ex VAT	986,32
Luggage space cover, Missing, E - Replace	288,00



Door F R, Bad repair, Acceptable	0,00
----------------------------------	------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Roof, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, 67 - Polish	0,00
--	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

