



SKODA Octavia: 1DLP915

Vinnnumber:	TMBCT21Z4D2009484	Versionname:	OCTAVIA BER Ambition
First Registrationdate:	18/06/2012	Fiscalpower:	DPF DSG 105PK Aut.
Expertise Mileage:	160803	Power Kw:	77
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2726
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 V Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 9 mm	Re.R.	Bridgestone: 9 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	2144,86
Wheel cover F R, Scratch(es), E - Replace	30,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------




Luggage space cover, Damaged, E - Replace 240,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68






Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bad repair, Acceptable 0,00



Wheel cover R R, Scratch(es), E - Replace 30,00







Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display