



**OPEL Corsa: 904BZI**

Vinnnumber:	<b>W0L0SDL68B4004127</b>	Versionname:	<b>CORSA BER ecoFLEX Enjoy FAP 95PK</b>
First Registrationdate:	<b>8/09/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>148214</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>9-8-2017</b>	Parking lot:	<b>2225</b>
Maintenance:	<b>136677 KM</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 H Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 8 mm</b>	Fr.R.	<b>Uniroyal: 8 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	845,18
-------------------	--------
























Ignition key, Broken, E - Replace	150,00
-----------------------------------	--------



Door frame R R, Dent(s), Acceptable	0,00
-------------------------------------	------



Bumper F, Scratch(es), It - Spot repair	115,56
---	--------

			Luggage space cover, Broken, E - Replace	10,00
			Roof, Scratch(es), Acceptable	0,00
			Wing F L, Dent(s), Acceptable	0,00
			Wing R L, Rust, It - Spot repair	115,56
			Bumper R, Dent(s) and scratch(es), Acceptable	0,00
			Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	280,06
			Wing F R, Scratch(es), Acceptable	0,00
			Door frame R L, Dent(s), Acceptable	0,00
			Wheel cover F L, Scratch(es), E - Replace	24,00
			Door F R, Scratch(es), Acceptable	0,00



Bodywork, Not original part, Remove lettering 150,00

