


RENAULT Grand Scenic: 1GQG089

Vinnumber:	VF1JZNAB650509571	Versionname:	GRAND SCENIC Energy Intens 7pl.130PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	116403	Power Kw:	96
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4231
Maintenance:	18400 KM 18 MOIS		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1218,98
-------------------	---------

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Wing F R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Bumper R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display

Door R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

Door R R, Scratch(es), 07 - Polish 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wheel aperture R R, Scratch(es), LI - Repair and paint (complete) 115,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper moulding F, Scratch(es), E - Replace 14,40



Tailgate, Dent(s), PDR - Knock out without painting 63,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

