



RENAULT Kangoo Express: 1EVN538

Vinnnumber:	VF1FW14BE48149533	Versionname:	KANGOO Expr. B/F Confort FAP (EU5) 75PK
First Registrationdate:	1/04/2013	Fiscalpower:	
Expertise Mileage:	128007	Power Kw:	55
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2308
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Rear parking sensors	
Type of headlighting:	Headlighting Halogen	Type of Tow bar:	No Tow bar
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection			
Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Power steering:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Handbrake:	OK	Transmission:	OK
		Lighting:	OK
		Wiperblades:	OK

Degree of wear				
	185/70/14/88 T LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment	
Emergency spare wheel:	Yes

Total cost ex VAT:	941,70
Ignition key, Missing, E - Replace:	150,00
<i>No pictures to display</i>	
Trunk door R R, Scratch(es), Acceptable:	0,00
<i>No pictures to display</i>	
Bumper R, Deformed / Strained, E - Replace:	329,40



Wing F L, Scratch(es), Acceptable:	0,00
<i>No pictures to display</i>	

Rearlight R , Broken, Acceptable	0,00
<i>No pictures to display</i>	
Bumper F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15

