


**TOYOTA YARIS: 1PRC027**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnnumber:                        | <b>VNKKD3D380A269089</b> | Versionname: | <b>1.5 VVT-I HYBRID BUSINESS PLUS AUTO</b> |
| First Registrationdate:            | <b>26/08/2016</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>27206</b>             | Power Kw:    | <b>54</b>                                  |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>                                |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                             |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                           |
| Fueltype:                          | <b>Hybrid Petrol</b>     | Oil level:   | <b>OK</b>                                  |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2122</b>                                |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                              |                 |                   |
|--------------------------------|------------------------------|-----------------|-------------------|
| Windows electric F             |                              | Luggage cover   |                   |
| Steering wheel multifunctional |                              | Type of Tow bar | <b>No Tow bar</b> |
| Radio multimedia               |                              |                 |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                 |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                 |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                 |                   |
| Type of climate control        | <b>Autom climate control</b> |                 |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                     |       |                     |
|---------------|----------------------------------|---------------------|-------|---------------------|
|               | <b>175/65/15/84 H LightMetal</b> |                     |       |                     |
| Summer tyres: | Fr.L.                            | <b>Dunlop: 6 mm</b> | Fr.R. | <b>Dunlop: 6 mm</b> |
|               | Re.L.                            | <b>Dunlop: 7 mm</b> | Re.R. | <b>Dunlop: 7 mm</b> |

**Assistance equipment**


|                       |            |
|-----------------------|------------|
| Emergency spare wheel | <b>Yes</b> |
|-----------------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 246,56 |
|-------------------|--------|

|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|   |        |
|---|--------|
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 246,56 |
|---|--------|



|                                   |      |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*