



SKODA Superb: 1FPO248			
Vinnnumber:	TMBJJ73T9E9016538	Versionname:	SUPERB COMBI Ambition 105PK
First Registrationdate:	16/09/2013	Fiscalpower:	
Expertise Mileage:	168252	Power Kw:	77
Bodytype:	Break	Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2423
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Dunlop: 3 mm	Re.R.	Dunlop: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			518,16
Bumper F L, Scratch(es), Acceptable			0,00
No pictures to display			
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)			254,16



Alloy rim R.L. Scratch(es), LI - Repair and paint (complete)			95,00
--	--	--	-------

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Protection plate M, Tear, E - Replace 74,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

