



DACIA Lodgy: 1EPN890			
Vinnumber:	UU1JSDBC648442542	Versionname:	LODGY Laur?ate 7pl. 107PK
First Registrationdate:	15/02/2013	Fiscalpower:	
Expertise Mileage:	139629	Power Kw:	79
Bodytype:		Body color	Dark Beige
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3507
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	565,44
Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Dent(s), PDR - Knock out without painting	63,00

Bumper R, Scratch(es), LI - Repair and paint (complete)	
169,44	





Rearview mirror housing L, Scratch(es), E - Replace 54,00



Luggage space cover, Damaged, E - Replace 192,00



Door F L, Dent(s), PDR - Knock out without painting 63,00



Wheel cover F R, Scratch(es), E - Replace 24,00

