


BMW 3 : 1KDB078

Vinnumber:	WBA3D91070J413819	Versionname:	
First Registrationdate:	18/03/2014	Fiscalpower:	
Expertise Mileage:	164467	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2606
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	659,56
-------------------	--------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	235,80
---------------------------------------------------------------------	--------



Console storage compartment, Scratch(es), Acceptable	0,00
------------------------------------------------------	------

No pictures to display

Bumper F L, Scratch(es), It - Spot repair	115,56
-------------------------------------------	--------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20

