



AUDI A3: 1HUJ495			
Vinnnumber:	<b>WAUZZZ8V9FA052535</b>	Versionname:	<b>A3 SB Attraction 110PK</b>
First Registrationdate:	<b>6/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>136202</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2325</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Steering wheel multifunction	Type of Tow bar <b>Tow bar removable</b>
Seats F heated	
Radio multimedia	
Type of headlighting <b>Headlighting Halogen</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining leather and alcantara</b>	
Type of climate control <b>Autom climate control</b>	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/55/16/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

Assistance equipment	
Emergency spare wheel	<b>Yes</b> Jack <b>Yes</b>
Total cost ex VAT	691,88
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Interior, Dirty, Cleaning 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

