



AUDI A6: 1FBP113			
Vinnumber:	WAUZZZ4G7DN148046	Versionname:	TDI
First Registrationdate:	16/05/2013	Fiscalpower:	
Expertise Mileage:	151063	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3123
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	SD Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/60/16/98 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			872,52
Bumper F, Scratch(es), LI - Repair and paint (complete)			254,16



Interior, Worn, Acceptable	0,00
----------------------------	-------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 302,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bodywork, Damaged, Acceptable 0,00



Ignition key, Not functioning (well), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Mirror side blinker L, Broken, E - Replace 31,20

