



AUDI A4: 1ERK353			
Vinnumber:	<b>WAUZZZ8K4DA205003</b>	Versionname:	<b>A4 BER TDi 120PK</b>
First Registrationdate:	<b>1/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>201682</b>	Power Kw:	<b>88</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2502</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>225/55/16/96 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

Assistance equipment	
Emergency spare wheel	<b>Yes</b>

Total cost ex VAT	1597,06
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bonnet, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper R, Scratch(es), 67 - Polish 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35

