


**AUDI A5: 1FGK436**

Vinnnumber:	<b>WAUZZZ8T9DA080136</b>	Versionname:	<b>A5 SB DPF Multitr.163PK Aut.</b>
First Registrationdate:	<b>21/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>168124</b>	Power Kw:	<b>120</b>
Bodytype:		Body color	<b>Dark Brown</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2322</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar <b>Tow bar removable</b>
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting <b>Headlighting Halogen</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining leather</b>	
Type of climate control <b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/98 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

**Assistance equipment**

 Emergency spare wheel **Yes**

Total cost ex VAT	751,86
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00




Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bad repair, Acceptable 0,00



Door F R, Bad repair, Acceptable 0,00

