


BMW X5: 1LCE177

Vinnnumber:	WBAK5610300N58703	Versionname:	3.0 XDRIVE40D 4WD AUTO
First Registrationdate:	18/08/2015	Fiscalpower:	
Expertise Mileage:	102152	Power Kw:	230
Bodytype:	SUV	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3128
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	275/40/20/106 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

 Runflat **Yes**

Total cost ex VAT	382,02
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bad repair, Acceptable	0,00


 Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) **382,02**



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Repaired, Acceptable	0,00
------------------------------	------

No pictures to display