



**FORD Transit 300M: 1FLJ284**

Vinnnumber:	<b>WF0XXXTFXDR04447</b>	Versionname:	<b>TRANSIT 300M B/F MWB</b>
First Registrationdate:	<b>6/08/2013</b>	Fiscalpower:	<b>Amb.DPF(EU5)125PK</b>
Expertise Mileage:	<b>34615</b>	Power Kw:	<b>92</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV16</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Type of Tow bar <b>No Tow bar</b>
Cruise Control	
Steering wheel multifunctional	
Type of headlighting <b>Headlighting Halogen</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining fabrics</b>	
Type of climate control <b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/70/15/104 R Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 7 mm</b>	Fr.R.	<b>Continental: 7 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	1326,14
-------------------	---------

Maintenance book, Missing, E - Replace	0,00
--	------

*No pictures to display*

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------



Trunk door R R, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Bumper R, Scratch(es), Smart repair 110,64



Sidewall FR (LCV), Dent(s) and scratch(es), It - Spot repair 115,56



Sidewall FL (LCV), Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Rearview mirror housing L, Scratch(es), Smart repair 110,64





Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 232,88



Wing F L, Dent(s), PDR - Knock out without painting 63,00



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display