



## CITROEN C4 Picasso: 1CSJ809

|                                    |                          |              |                              |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber:                        | <b>VF7UA9HR8CJ521178</b> | Versionname: | <b>GR.C4 PICASSO Bus.GPS</b> |
| First Registrationdate:            | <b>16/02/2012</b>        | Fiscalpower: | <b>FAP 112PK</b>             |
| Expertise Mileage:                 | <b>180093</b>            | Power Kw:    | <b>82</b>                    |
| Bodytype:                          | <b>MPV</b>               | Body color:  | <b>Blue</b>                  |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>             |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2115</b>                  |
| Number of doors:                   | <b>5</b>                 |              |                              |
| Number of seats:                   | <b>7</b>                 |              |                              |
| Number head rests:                 | <b>7</b>                 |              |                              |
| Rims summer:                       | <b>Aluminium</b>         |              |                              |
| Category:                          | <b>Passenger Car</b>     |              |                              |
| Oil level:                         | <b>OK</b>                |              |                              |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                              |

## Options

|                                |                              |                          |
|--------------------------------|------------------------------|--------------------------|
| Radio CD                       | Central consol F             |                          |
| TV/DVD screen R                | Luggage cover                |                          |
| Windows electric F             | Rear parking sensors         |                          |
| Windows electric R             | Type of Tow bar              | <b>Tow bar removable</b> |
| Cruise Control                 |                              |                          |
| Steering wheel multifunctional |                              |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                          |
| Type of climate control        | <b>Autom climate control</b> |                          |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                 |                      |       |                      |
|---------------|---------------------------------|----------------------|-------|----------------------|
|               | <b>215/5/16/93 V LightMetal</b> |                      |       |                      |
| Summer tyres: | Fr.L.                           | <b>Pirelli: 4 mm</b> | Fr.R. | <b>Pirelli: 4 mm</b> |
|               | Re.L.                           | <b>Fulda: 7 mm</b>   | Re.R. | <b>Fulda: 7 mm</b>   |

## Assistance equipment

|  |            |
|--|------------|
| Emergency spare wheel                    | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |
| Number of charging cables (rapid charge) | <b>0</b>   |

Total cost ex VAT 1280,64

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing L, Scratch(es), 67 - Polish 0,00

No pictures to display

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Interior, Dirty, Cleaning 0,00



Door F L, Scratch(es), 67 - Polish 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

