



<b>FORD Fiesta: 1FAH070</b>			
Vinnumber:	<b>WF0CXXGAKCDP17277</b>	Versionname:	<b>FIESTA BER Trend 75PK</b>
First Registrationdate:	<b>6/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>26942</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3117</b>
Number of doors:	<b>3</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>No GPS</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>195/50/15/82 H Steel</b>			
Summer tyres:	Fr.L.	<b>Kleber: 1 mm</b>	Fr.R.	<b>Kleber: 1 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	<b>1371,38</b>
Sill outer L, Dent(s) and scratch(es), Le - Replace and paint	<b>579,20</b>



Rearview mirror housing L, Scratch(es), E - Replace	<b>64,00</b>
---	--------------



Wheel cover F R, Scratch(es), E - Replace	<b>24,00</b>
---	--------------



Bonnet, Scratch(es), LI - Repair and paint (complete) 232,06



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F L, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s), LI - Repair and paint (complete) 254,68



Wheel cover R R, Scratch(es), E - Replace 24,00

