


BMW 3: 1HRU192

Vinnnumber:	WBA3K91090F935697	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	16/09/2014	Fiscalpower:	
Expertise Mileage:	100226	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2328
Maintenance:	SERVICE IN 12000KM 9 2019		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	No GPS
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		190,00
Seat cover R, Stain, Acceptable		0,00
<i>No pictures to display</i>		
Roof, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper Trim F, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

