



CITROEN C4 Picasso: 1GQL309

Vinnumber:	VF73A9HC8DJ887547	Versionname:	GR.C4 PICASSO Seduction
First Registrationdate:	1/04/2014	Fiscalpower:	115PK
Expertise Mileage:	126561	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE IN 21300KM	Parking lot:	3423
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	756,30
-------------------	--------

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

481,50

