



**PEUGEOT 5008: 1FQT856**

|                                    |                          |              |                              |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber:                        | <b>VF30A9HD8DS175238</b> | Versionname: | <b>5008 Active FAP 115PK</b> |
| First Registrationdate:            | <b>26/09/2013</b>        | Fiscalpower: |                              |
| Expertise Mileage:                 | <b>130782</b>            | Power Kw:    | <b>84</b>                    |
| Bodytype:                          |                          | Body color:  | <b>Silver</b>                |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3622</b>                  |
| Number of doors:                   | <b>5</b>                 |              |                              |
| Number of seats:                   | <b>5</b>                 |              |                              |
| Number head rests:                 | <b>5</b>                 |              |                              |
| Rims summer:                       | <b>Steel</b>             |              |                              |
| Category:                          | <b>Passenger Car</b>     |              |                              |
| Oil level:                         | <b>OK</b>                |              |                              |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                              |

**Options**

|                         |                              |                      |
|-------------------------|------------------------------|----------------------|
| Radio CD                |                              | Central consol F     |
| GPS storage             |                              | Luggage cover        |
| GPS storage             | <b>HD</b>                    | Rear parking sensors |
| Windows electric F      |                              |                      |
| Windows electric R      |                              |                      |
| Cruise Control          |                              |                      |
| Type of headlighting    | <b>Headlighting Halogen</b>  |                      |
| Type of GPS             | <b>GPS big screen color</b>  |                      |
| Type of Lining          | <b>Lining fabrics</b>        |                      |
| Type of climate control | <b>Autom climate control</b> |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/16/92 H Steel</b> |                       |       |                       |
| Summer tyres: | Fr.L.                       | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                       | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |       |
|-------------------|-------|
| Total cost ex VAT | 93,00 |
|-------------------|-------|

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|





Rear window, Scratch(es), Acceptable 0,00



Rocker panel inner R R, Broken, Acceptable 0,00



Rocker panel inner R L, Dent(s), Acceptable 0,00



Rocker panel inner F R, Dent(s), Acceptable 0,00



Rocker panel inner F L, Scratch(es), Acceptable 0,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Acceptable 0,00



Internal Boot Lining R, Scratch(es), Acceptable 0,00



Tailgate, Dent(s), PDR - Knock out without painting 63,00



Trunk lid covering R, Scratch(es), Acceptable 0,00



Wheel cover F R, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00



Rearview mirror L complete, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Wheel cover R R, Missing, E - Replace 30,00



Wheel cover R L, Scratch(es), Acceptable 0,00

