



RENAULT GRAND SCENIC: 1LAE827

Vinnnumber:	VF1JZ898H53539597	Versionname:	1.5 ENERGY DCI 110 BOSE EDITION 7P
First Registrationdate:	31/07/2015	Fiscalpower:	
Expertise Mileage:	169004	Power Kw:	81
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2625
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes
Total cost ex VAT	1767,03
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00





Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wing R L, Scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

