



**PORSCHE Cayenne: 1FWZ440**

Vinnumber:	<b>WP1ZZZ92ZELA36464</b>	Versionname:	<b>CAYENNE DPF Tiptr.S 211PK Aut.</b>
First Registrationdate:	<b>22/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>168835</b>	Power Kw:	<b>155</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3829</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Central consol F	
Radio multimedia		Luggage cover	
Type of headlighting	<b>Headlighting Halogen</b>	Front parking sensors	
Type of GPS	<b>GPS big screen color</b>	Rear parking sensors	
Type of Lining	<b>Lining leather</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>275/45/20/110 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1151,39</b>
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00





Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Foglight R, Deformed / Strained, E - Replace 156,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display