



**OPEL Insignia: 1GHS467**

Vinnumber:	<b>W0LGM6ER5E1039759</b>	Versionname:	<b>INSIGNIA BER ecoFLEX Edition 120PK</b>
First Registrationdate:	<b>11/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>105869</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3412</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/95 V Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	2578,68
-------------------	---------

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Wheel cover F R, Broken, E - Replace 30,00



Wing R L, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80




Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Rearview mirror R complete, Broken, E - Replace 168,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Sill outer R, Dent(s), LI - Repair and paint (complete) 310,50



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

