


**PEUGEOT EXPERT TEPEE: 1KPD653**

Vinnnumber:	<b>VF3XDAH8FZ028663</b>	Versionname:	<b>2.0 L2H1 72KW TEPEE</b>
First Registrationdate:	<b>8/06/2015</b>	Fiscalpower:	<b>ACCESS 6 PL</b>
Expertise Mileage:	<b>49562</b>	Power Kw:	<b>72</b>
Bodytype:	<b>Bus</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV19</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>8</b>		
Number head rests:	<b>8</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F:		Rear parking sensors:	
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>No GPS</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning:	<b>OK</b>	Battery functioning:	<b>Yes</b>
Tires wear profile:	<b>OK</b>	Power steering:	<b>Yes</b>
Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Wiper fluid level:	<b>OK</b>
Handbrake:	<b>OK</b>	Transmission:	<b>OK</b>
		Lighting:	<b>OK</b>
		Wiperblades:	<b>OK</b>

**Degree of wear**

	<b>215/60/16/101 T Steel</b>			
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
--------------	------------	-------	------------

<b>Total cost ex VAT</b>	<b>1248,13</b>
Bonnet, Dent(s), PDR - Knock out without painting	63,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	165,13



Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover R R, Damaged, E - Replace	300,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R L, Deformed / Strained, Acceptable 0,00

No pictures to display

Floor covering R, Hole, E - Replace 237,00



Inner door handle R L, Broken, E - Replace 33,00



Seat cover F R, Damaged, E - Replace 300,00

