


NISSAN QASHQAI: 1KBR362

Vinnumber:	SJNFDAJ11U1320751	Versionname:	1.6 DCI TEKNA
First Registrationdate:	26/03/2015	Fiscalpower:	
Expertise Mileage:	63848	Power Kw:	96
Bodytype:	SUV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2828
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/17/95 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 590,35

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display
Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display
Door F L, Dent(s) and scratch(es), Le - Replace and paint 0,00



Rear bulkhead lining, Scratch(es), E - Replace 64,00




Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror glass R, Broken, E - Replace 18,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display