



**MERCEDES CLA SHOOTING BRAKE: 1KSE839**

|                                   |                          |              |                                       |
|-----------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnnumber:                       | <b>WDD1179081N225606</b> | Versionname: | <b>2.1 CLA 200 CDI SHOOTING BRAKE</b> |
| First Registrationdate:           | <b>22/06/2015</b>        | Fiscalpower: |                                       |
| Expertise Mileage:                | <b>164989</b>            | Power Kw:    | <b>100</b>                            |
| Bodytype:                         |                          | Body color   | <b>Dark Grey</b>                      |
| Gearbox:                          | <b>Automatic</b>         | Paint type   | <b>Metalic</b>                        |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                      |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                             |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>3610</b>                           |
| Number of doors                   | <b>5</b>                 |              |                                       |
| Number of seats                   | <b>5</b>                 |              |                                       |
| Number head rests                 | <b>5</b>                 |              |                                       |
| Rims summer                       | <b>Aluminium</b>         |              |                                       |
| Category                          | <b>Passenger Car</b>     |              |                                       |
| Oil level                         | <b>OK</b>                |              |                                       |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                       |

**Options**

|                                |                                       |
|--------------------------------|---------------------------------------|
| Radio CD                       | Central consol F                      |
| Windows electric F             | Luggage cover                         |
| Windows electric R             |                                       |
| Cruise Control                 |                                       |
| Steering wheel multifunctional |                                       |
| Radio multimedia               |                                       |
| Type of headlighting           | <b>Headlighting Halogen</b>           |
| Type of GPS                    | <b>GPS big screen color</b>           |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |
| Type of climate control        | <b>Manual climate control</b>         |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Pirelli: 3 mm</b>  | Fr.R. | <b>Pirelli: 3 mm</b>  |
|               | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |        |
|---|--------|
| Total cost ex VAT                                       | 211,80 |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |



|                                   |      |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display