



MERCEDES CLA 200 CDI: 1HTC479

Vinnnumber:	WDD1173081N142189	Versionname:	CLA BER 200 CDI(EU6)
First Registrationdate:	25/09/2014	Fiscalpower:	136PK
Expertise Mileage:	149848	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1114
Maintenance:	A5 IN 135 DAYS		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Front parking sensors
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-leather
Type of climate control:	Manual climate control
Level control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 Y LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	No
------------	------------	------------	-----------

Total cost ex VAT 1199,78

Side window trim F R, Deformed / Strained, E - Replace 101,94



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00



Door R L, Repaired, P - Check

0,00



Alloy rim F L, Scratch(es), Acceptable

0,00



Floor covering F R, Burned, Smart repair

64,32



Compressor, Missing, E - Replace

100,00



Wing R L, Dent(s), Acceptable

0,00



Central pillar L, Dent(s), Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00



Door panel R R, Hole, E - Replace

114,00





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel F L, Burned, E - Replace 114,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Full screen GPS, Not functioning (well), P - Check 0,00



Floor covering F L, Burned, Smart repair 64,32



Central pillar R, Dent(s), Acceptable 0,00

