



## VOLKSWAGEN Touran: 1HLG195

Vinnnumber:	<b>WVGZZZ1TZFW006112</b>	Versionname:	<b>TOURAN Trendline BMT St&amp;St 7pl.105PK</b>
First Registrationdate:	<b>19/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>130253</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3813</b>
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Semperit: 5 mm</b>	Fr.R.	<b>Semperit: 5 mm</b>
	Re.L.	<b>Kleber: 5 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	1047,92
-------------------	---------

Door R R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Hole, Smart repair 64,32



Wing R L, Dent(s), PDR - Knock out without painting 63,00



Trunk lid covering R, Scratch(es), E - Replace 149,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

*No pictures to display*