


SKODA Octavia: 1HAU113

Vinnnumber:	TMBJG7NE3E0210676	Versionname:	OCTAVIA COMBI
First Registrationdate:	5/06/2014	Fiscalpower:	GreenLine Ambition 110PK
Expertise Mileage:	150366	Power Kw:	81
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2104
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	No
------------	------------	------------	-----------

Total cost ex VAT	0,00
-------------------	------

Compressor, Missing, E - Replace	0,00
----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)	0,00
---	------





Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	0,00
---	------

