


SKODA OCTAVIA COMBI: 1 SPC317

Vinnumber:	TMBJ9NE5J0085350	Versionname:	2.0 CRTDI 110kW GreenTec Style
First Registrationdate:	19/06/2017	Fiscalpower:	
Expertise Mileage:	36794	Power Kw:	110
Bodytype:	Break	Body color	Beige
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2602
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Seats electric F L
Windows electric R	Seats electric F R
Cruise Control	Central consol F
Steering wheel multifunction	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 T LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	337,80
Door R R, Dent(s), PDR - Knock out without painting	63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R R, Dent(s), PDR - Knock out without painting

63,00



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display