


**OPEL Vivaro 2700: 1EPK841**

|                         |                                 |              |                                           |
|-------------------------|---------------------------------|--------------|-------------------------------------------|
| Vinnnumber:             | <b>WOLF7A1A6DV606071</b>        | Versionname: | <b>VIVARO 2700 B/F SWB L1H1(EU5)115PK</b> |
| First Registrationdate: | <b>14/02/2013</b>               | Fiscalpower: |                                           |
| Expertise Mileage:      | <b>248933</b>                   | Power Kw:    | <b>84</b>                                 |
| Bodytype:               | <b>Transporter</b>              | Body color:  | <b>Red</b>                                |
| Gearbox:                | <b>MAN 6 VIT</b>                | Paint type:  | <b>Metalic</b>                            |
| Transmission:           |                                 | Rims summer: | <b>Steel</b>                              |
| Fueltype:               | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                 |
| Battery functioning:    | <b>Yes</b>                      | Parking lot: | <b>2733</b>                               |
| Number of doors:        | <b>5</b>                        |              |                                           |
| Number of seats:        | <b>3</b>                        |              |                                           |
| Number head rests:      | <b>3</b>                        |              |                                           |
| Rims summer:            | <b>Steel</b>                    |              |                                           |
| Category:               | <b>Light Commercial Vehicle</b> |              |                                           |
| Oil level:              | <b>OK</b>                       |              |                                           |

**Options**

|                         |                               |                   |
|-------------------------|-------------------------------|-------------------|
| Radio CD                | Type of Tow bar               | <b>No Tow bar</b> |
| Windows electric F      |                               |                   |
| Radio multimedia        |                               |                   |
| Type of headlighting    | <b>Headlighting Halogen</b>   |                   |
| Type of GPS             | <b>GPS big screen color</b>   |                   |
| Type of Lining          | <b>Lining fabrics</b>         |                   |
| Type of climate control | <b>Manual climate control</b> |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                              |                     |       |                     |
|---------------|------------------------------|---------------------|-------|---------------------|
|               | <b>205/65/16/107 T Steel</b> |                     |       |                     |
| Summer tyres: | Fr.L.                        | <b>Kleber: 7 mm</b> | Fr.R. | <b>Kleber: 7 mm</b> |
|               | Re.L.                        | <b>Kleber: 4 mm</b> | Re.R. | <b>Kleber: 4 mm</b> |

**Assistance equipment**

|             |            |
|-------------|------------|
| Spare wheel | <b>Yes</b> |
|-------------|------------|

|                                     |        |
|-------------------------------------|--------|
| Total cost ex VAT                   | 645,69 |
| Bumper F, Scratch(es), Smart repair | 110,64 |



|                                                    |      |
|----------------------------------------------------|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------------------|------|



*No pictures to display*

|                                                  |        |
|--------------------------------------------------|--------|
| Sidewall FL (LCV), Scratch(es), It - Spot repair | 115,56 |
|--------------------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                                                                    |        |
|------------------------------------------------------------------------------------|--------|
| Bumper R, Dent(s), Smart repair                                                    | 110,64 |
|  |        |
| Wing R R, Scratch(es), Acceptable                                                  | 0,00   |
| <i>No pictures to display</i>                                                      |        |
| Trunk door R L, Dent(s) and scratch(es), Acceptable                                | 0,00   |
| <i>No pictures to display</i>                                                      |        |
| Ignition key, Missing, E - Replace                                                 | 150,00 |
| <i>No pictures to display</i>                                                      |        |
| Bumper F, Scratch(es), LI - Repair and paint (complete)                            | 158,85 |
|  |        |