


SKODA OCTAVIA COMBI: 1KKF351

Vinnnumber:	TMBLG7NE3F0226922	Versionname:	1.6 CRTDI 77KW 4WD GREENTEC AMBITION
First Registrationdate:	19/05/2015	Fiscalpower:	
Expertise Mileage:	197898	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2627
Maintenance	10400KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	607,40
-------------------	--------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Outer door handle F R, Scratch(es), Acceptable	0,00
--	------



Gear shift lever knob, Worn, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), It - Spot repair 115,56



Wheel cover F L, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), It - Spot repair 115,56



Wing R L, Dent(s) and scratch(es), Acceptable 0,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wheel cover F R, Missing, E - Replace 30,00



Interior, Dirty, Cleaning 125,00





Door panel R L, Scratch(es), Smart repair 110,64



Windscreen, Stone chip(s), Windscreen repair 0,00



Wheel cover R R, Scratch(es), Acceptable 0,00

