



VOLKSWAGEN Crafter 35 MWB hoog dak: 1FLC522

Vinnumber:	WV1ZZZ2EZD6024868	Versionname:	CRAFTER 35 B/F MWB HR 109PK
First Registrationdate:	2/08/2013	Fiscalpower:	
Expertise Mileage:	1	Power Kw:	80
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of Lining	Lining fabrics	Type of Tow bar	No Tow bar
Type of climate control	Manual climate control		

Limited Technical Inspection

Degree of wear

	235/65/16/115 R Steel			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 9,9 mm	Re.R.	Continental: 9,9 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1207,17
-------------------	----------------

Door F R, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

<i>No pictures to display</i>	
Engine, Not functioning (well), P - Check	0,00



Seat cover F L, Hole, E - Replace	300,00
-----------------------------------	---------------



Steering wheel, Worn, Acceptable 0,00



Wing R L, Rust, LI - Repair and paint (complete) 231,15



Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete) 526,02




Ignition key, Missing, E - Replace 150,00



Sidewall RR (LCV), Dent(s), LI - Repair and paint (complete) 0,00





Trunk door R R, Scratch(es), Acceptable

0,00

No pictures to display