


RENAULT Megane: 1GJG003

Vinnnumber:	VF1KZ140650159527	Versionname:	MEGANE BRE Energy Bose Ed.110PK
First Registrationdate:	21/02/2014	Fiscalpower:	
Expertise Mileage:	43222	Power Kw:	81
Bodytype:		Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3304
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/17/89 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	723,68
-------------------	--------

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper spoiler F, Scratch(es), E - Replace 42,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

