



VOLKSWAGEN POLO: 1JXP954

Vinnnumber:	WVWZZZ6RZFY263007	Versionname:	1.4 TDI 66KW TRENDLINE BMT
First Registrationdate:	13/03/2015	Fiscalpower:	
Expertise Mileage:	84395	Power Kw:	66
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3112
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
Windows electric F		Luggage cover
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/70/14/84 T Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	363,57
-------------------	--------

Seat cover F L, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Door F R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Crack, Acceptable	0,00
-----------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof, Dent(s), PDR - Knock out without painting 82,80



Seat cover R R, Stain, Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), E - Replace 48,33



Wing F R, Chemical polution, Acceptable 0,00

No pictures to display

Wing F L, Chemical polution, 67 - Polish 0,00

No pictures to display

Floor covering F L, Burned, Acceptable 0,00

No pictures to display

Roof, Chemical polution, 67 - Polish 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44

