



| MERCEDES A: 1LBV119 | | | |
|------------------------------------|--------------------------|--------------|----------------------|
| Vinnumber: | WDD1760121V090670 | Versionname: | 1.5 A 180 CDI |
| First Registrationdate: | 13/08/2015 | Fiscalpower: | |
| Expertise Mileage: | 67647 | Power Kw: | 80 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3122 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | | | |
|--------------------------------|-------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | No Tow bar |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|---------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | NOT OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/95 V Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

| Assistance equipment | | | |
|---|------------|------------|--------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 90,00 |
| Wheel cover R R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Wheel cover F L, Scratch(es), E - Replace | | | 30,00 |



| | | | |
|---|--|--|--------------|
| Wheel cover R L, Scratch(es), E - Replace | | | 30,00 |
|---|--|--|--------------|

Wheel cover R L, Scratch(es), E - Replace 30,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00

