



MERCEDES E: 1HRB903

Vinnnumber:	WDD2120011B063346	Versionname:	E BER 220 BlueTEC BE
First Registrationdate:	10/09/2014	Fiscalpower:	Edit.163PK Aut.
Expertise Mileage:	93776	Power Kw:	120
Bodytype:	Berline	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3626
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


245/45/17/95 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 8 mm	Fr.R.	Bridgestone: 8 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 646,23

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Alloy rim R R polished, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>		
Alloy rim F R polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door frame R R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)		382,02

