


MERCEDES A: 1LBV113

Vinnumber:	WDD1760121V090167	Versionname:	1.5 A 180 CDI
First Registrationdate:	13/08/2015	Fiscalpower:	
Expertise Mileage:	70867	Power Kw:	80
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3504
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/95 V Steel				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Bonnet, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Roof, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Wing R R, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover F L, Scratch(es), Acceptable			0,00

No pictures to display