


**NISSAN Qashqai: 1HSB536**

Vinnnumber:	<b>SJNFAAJ11U1190585</b>	Versionname:	<b>QASHQAI 2WD Tekna 110PK</b>
First Registrationdate:	<b>18/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>172423</b>	Power Kw:	<b>81</b>
Bodytype:	<b>SUV</b>	Body color	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3525</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/17/96 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Firestone: 7 mm</b>	Fr.R.	<b>Firestone: 7 mm</b>
	Re.L.	<b>Bridgestone: 7 mm</b>	Re.R.	<b>Bridgestone: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	608,43
-------------------	--------

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------




Wing R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

*No pictures to display*

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		318,35
		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		