



RENAULT Kangoo Express: 1FLF713

Vinnnumber:	VF1FW58H549408143	Versionname:	KANGOO EXPR.MAXI Energy Gr.Conf.90PK
First Registrationdate:	5/08/2013	Fiscalpower:	
Expertise Mileage:	1	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel		
Maintenance:	GEEN STROOM		
Battery functioning:	No		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Type of headlighting:	Headlighting Halogen	Type of Tow bar:	No Tow bar
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Battery functioning **No**

Degree of wear

	195/65/15/95 T Steel			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Spare wheel **Yes** Jack **Yes**

Total cost ex VAT **908,14**

Seat cover F L, Stain, Cleaning **25,00**



Bodywork, Not original part, Acceptable **0,00**



Wheel cover F R, Broken, E - Replace **22,50**



Bodywork, Damaged, Acceptable **0,00**



Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Certificate Of Conformity, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door frame F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F L, Scratch(es), Smart repair	110,64



Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Registration Document, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Backrest cover F L, Tear, E - Replace	300,00

