



RENAULT Trafic: 1AXT140			
Vinnnumber:	<b>VF1JLB7B6BV410485</b>	Versionname:	<b>TRAFIC PAS.Phys.III L2H1</b>
First Registrationdate:	<b>13/04/2011</b>	Fiscalpower:	<b>Expr.FAP 115PK</b>
Expertise Mileage:	<b>75895</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV18</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>8</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

Options			
Windows electric F		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>215/65/16/104 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	1432,81
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Crack, Le - Replace and paint	506,25



Seat cover R R, Deformed / Strained, E - Replace	300,00
--	--------



Backrest cover R L, Damaged, E - Replace	160,00
--	--------



Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



De-icer nozzle internal R, Broken, E - Replace 153,00



Engine, Not functioning (well), Acceptable 0,00

No pictures to display

De-icer nozzle internal L, Broken, E - Replace 153,00



Ceiling, Damaged, Acceptable 0,00

No pictures to display

Headrest F R, Missing, E - Replace 45,00

