



VOLVO XC60: 1FAH597			
Vinnnumber:	YV1DZ31A1D2437593	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	6/05/2013	Fiscalpower:	
Expertise Mileage:	130542	Power Kw:	100
Bodytype:	SUV	Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2712
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting:	Headlighting Halogen	Type of Tow bar:	Tow bar removable
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/60/18/103 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			110,64
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Sill outer R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy Rims (all), Rust, Acceptable			0,00



Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			

Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door moulding Lower R R, Scratch(es), Smart repair	110,64

