


**AUDI A3: 1FPQ763**

Vinnnumber:	<b>WAUZZZ8V6EA053155</b>	Versionname:	<b>A3 SB Ambition 105PK</b>
First Registrationdate:	<b>17/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>78193</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>4708</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1091,73</b>
Bonnet, Stone chip(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), 67 - Polish	<b>0,00</b>
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	<b>150,00</b>
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door R R, Scratch(es), LI - Repair and paint (complete)	<b>318,35</b>



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bagage rack, Deformed / Strained, Repair/replace (lump sum) 0,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Bumper F, Scratch(es), LI - Repair and paint (complete) 0,00

