


**AUDI A1: 1FRJ347**

|                                    |                          |              |                  |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber:                         | <b>WAUZZZ8X5EB034415</b> | Versionname: |                  |
| First Registrationdate:            | <b>1/10/2013</b>         | Fiscalpower: |                  |
| Expertise Mileage:                 | <b>101091</b>            | Power Kw:    | <b>63</b>        |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Black</b>     |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:                          | <b>Petrol</b>            | Oil level:   | <b>OK</b>        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4610</b>      |
| Number of doors:                   | <b>5</b>                 |              |                  |
| Number of seats:                   | <b>4</b>                 |              |                  |
| Number head rests:                 | <b>4</b>                 |              |                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                  |
| Category:                          | <b>Passenger Car</b>     |              |                  |
| Oil level:                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                  |

**Options**

|                                |                              |                      |  |
|--------------------------------|------------------------------|----------------------|--|
| Radio CD                       |                              | Luggage cover        |  |
| Windows electric F             |                              | Rear parking sensors |  |
| Windows electric R             |                              |                      |  |
| Steering wheel multifunctional |                              |                      |  |
| Radio multimedia               |                              |                      |  |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |  |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |  |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |  |
| Type of climate control        | <b>Autom climate control</b> |                      |  |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/15/88 W LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>229,44</b> |
|-------------------|---------------|

|   |              |
|---|--------------|
| Luggage space cover, Missing, E - Replace | <b>60,00</b> |
|---|--------------|



|                                |             |
|--------------------------------|-------------|
| Wing R R, Repaired, Acceptable | <b>0,00</b> |
|--------------------------------|-------------|

*No pictures to display*

|                                   |             |
|-----------------------------------|-------------|
| Bumper F, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|   |               |
|---|---------------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | <b>169,44</b> |
|---|---------------|



Tailgate, Dent(s), Acceptable

0,00

*No pictures to display*