



BMW 3: 1GMC941

Vinnnumber:**WBA3K11030F830686**

First Registrationdate:**7/03/2014**

Expertise Mileage:**133137**

Bodytype:

Gearbox:**MAN 6 VIT**

Transmission:**Front**

Fueltype:**Diesel**

Maintenance**DANS 15000KM**

Maintenance**OK**

Battery functioning**Yes**

Number of doors**5**

Number of seats**5**

Number head rests**5**

Rims summer**Aluminium**

Category**Passenger Car**

Oil level**OK**

Registration Certificate Car (BE)**Yes**

Versionname:**3 TOURING 318d 136PK**

Fiscalpower:

Power Kw:**100**

Body color**Beige**

Paint type**Metalic**

Rims summer**Aluminium**

Oil level**OK**

Parking lot**2506**

Options

Radio CD

GPS storage

GPS storage

Windows electric F

Windows electric R

Cruise Control

Steering wheel multifunctional

Radio multimedia

Type of headlighting**Headlighting Halogen**

Type of GPS**GPS big screen color**

Type of Lining**Lining leather**

Type of climate control**Autom climate control**

Central consol F

Luggage cover

Rear parking sensors

Type of Tow bar**No Tow bar**

Limited Technical Inspection

Airco functioning**OK**

Tires wear profile**OK**

Idle position**OK**

Engine startingtime**OK**

Exhaust gass**OK**

Handbrake**OK**

Battery functioning**Yes**

Power steering**Yes**

Sound engine**OK**

Clutch test**OK**

Wiper fluid level**OK**

Transmission**OK**

Lighting**OK**

Wiperblades**OK**

Degree of wear

Summer tyres:

205/60/16/92 W LightMetal

Fr.L.**Michelin: 5 mm**

Fr.R.**Michelin: 5 mm**

Re.L.**Michelin: 5 mm**

Re.R.**Michelin: 5 mm**

Assistance equipment

Repair kit**Yes**

Compressor**Yes**

Total cost ex VAT

358,00

Bumper R, Dent(s), Acceptable

0,00

Rocker panel inner F L, Dent(s), Acceptable

0,00



Door panel F R, Tear, E - Replace

114,00



Door panel F L, Hole, Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F L, Worn, Acceptable

0,00



Door R R, Dent(s), Acceptable

0,00



Sill outer R, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Wing F R, Dent(s), Acceptable

0,00



Door seal F L, Deformed / Strained, Acceptable

0,00



Door seal F R, Broken, E - Replace

54,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

